



CAT HOUSE ASSEMBLY INSTRUCTIONS










N843P252383

N843P252384
























N843P252383










 9 x1	 10 x2	 13 x1
 14 x1	 17 x1	 18 x1
 24 x7	 25 x7	 26 x12

N843P252384



 1 x1	 2 x1	 3 x1
 4 x1	 5 x1	 6 x1

N843P252384


 7 x1	 8 x1	 11 x1
 12 x1	 15 x1	 16 x1
 19 x1	 20 x1	 21 x1
 22 x2	 23 x4	 26 x2
 27 x14	 Hardware	

A		M3.5x50mm	41
B		M3.5x35mm	46
C		M3.5x30mm	176
D		M3.5x20mm	4
E		M3.5x12mm	42
F			6
G			3
H			4
			


Step1




Step2





Step3




	Ax4
---	-----

Step4





	Ax6
---	-----

Step5





Ax4

Step6





Ax6

Step7





Ax2

Step8





Ax3


Step9




Step10





Step11





	Bx8
---	------------

Step12






	Bx14
---	-------------

Step13





Bx16

Step14




Dx4

Step15




Cx8

Step16





Fx2




Ex8


Step17




	Ax2
---	-----

Step18




	Fx4		Ex16
---	-----	---	------

Step19




Gx3






Ex12

Step20




x7





Cx168

Step21



Step22



	Hx4		Ex8
---	-----	---	-----