



DJYC2510


ASSEMBLY INTRODUCTION



Exploded View



Fitting




A x 65
M6 x 35 mm



B x 65
φ15 x 9.5 mm



C x 50
φ6 x 30 mm



D x 13
φ4 x 35 mm



E x 40
φ3 x 12mm



F x 16
φ5 x 20 mm



G x 2



H x 4
φ4 x 12 mm




I x 2
φ6 x 30 mm



J x 2
φ4 x 40 mm




K x 24
φ3.5 x 12 mm




L x 4



M x 4



N x 24
φ3 x 14 mm




O x 2




P x 4
φ3 x 14 mm



Q x 10
M4 x 14mm




R x 5




CL x 1
350 mm



CR x 1
350 mm







DL x 1
350 mm




DR x 1
350 mm


Step 1



E x 6
 $\varnothing 3 \times 12 \text{ mm}$





CL x 1
350 mm




CR x 1
350 mm

Step 2




A x 10
M6 x 35 mm


Step 3




Step 4




Step 5





Step 6




Step 7




Step 8







Step 9




Step 10




Step 11




Step 12






Step 13




Step 14



x2




Step 15




K x 16
 $\varnothing 3.5 \times 12 \text{ mm}$

Step 16





D x 5
 $\varnothing 4 \times 35 \text{ mm}$

Step 17




Step 18




A x 5
M6 x 35 mm

Step 19




B x 5
φ15 x 9.5 mm

Step 20






Q x 2
M4 x 14mm




R x 1


Step 21



E x 6
φ3 x 12mm




DL x 1
350 mm





DR x 1
350 mm





Step 22






Step 23






Step 24






Step 25





Step 26





Step 27







Step 28




Step 29



Step 30




Step 31



E x 12
 $\phi 3 \times 12\text{mm}$

Step 32



F x 16
 $\phi 5 \times 20\text{mm}$