

# WYNN PULL OUT TABLE

Assembly instructions:

## PART LISTS

| NO. | DESCRIPTION      | IMAGE                                                                             | Q'TY |
|-----|------------------|-----------------------------------------------------------------------------------|------|
| P1  | TABLE TOP        |  | 1PC  |
| P2  | METAL BASE       |  | 1PC  |
| P3  | METAL BASE SIDE  |  | 2PCS |
| P4  | METAL BASE FRONT |  | 1PC  |

## HARDWARE LISTS


| NO. | DESCRIPTION        | IMAGE                                                                             | Q'TY  |
|-----|--------------------|-----------------------------------------------------------------------------------|-------|
| H1  | BOLT               |  | 10PCS |
| H2  | SPRING WASHER 1/4" |  | 10PCS |
| H3  | FLAT WASHER 1/4"   |  | 10PCS |
| H4  | ALLEN KEY          |  | 1PC   |

**NOTE:** PO# is located underneath/ inside of each item. Please be prepared to provide this # should any claim be necessary.


**CAUTION:** Item is heavy assembly should be performed by two people.

Estimate assenbly time:5 minutes


1



2



3



ASSEMBLY COMPLETED